

Stevensville

Evaluation of the **Stevensville Airport** yielded the following PCI values.

Section	Critical PCI	Surveyed PCIs				Predicted PCIs	
		1988	1991	1994	1997	2002	2007
A-1	55	XX	XX	79	81	63	53
A-2	55			100	97	78	59
R-1	50	XX	XX	89	85	68	56
T-1	50	XX	XX	85	86	69	56
T-3	55			100	98	80	67

Pavement Condition Index (PCI) to **Pavement Condition Rating** conversion:

0 ≤ **Failed** ≤ 10 < **Very Poor** ≤ 25 < **Poor** ≤ 40 < **Fair** ≤ 55 < **Good** ≤ 70 < **Very Good** ≤ 85 < **Excellent** ≤ 100

"XX" in PCI columns indicates previous PCI values have been voided to account for new construction.

No entry in PCI columns indicates no inspection of the pavement section for the year.

PCI predictions are based on the assumption that current maintenance practices will continue with no major reconstruction.

All of your pavements are rated as "very good" or above. With continued maintenance, all of your pavement is projected to remain above critical PCI values for nearly ten years.